### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Client ID: M04514
Date Received: 08/20/09
Date Extracted: 08/20/09
Date Analyzed: 08/24/09
Matrix: Water
Units: ug/L (ppb)

Client: Project: Lab ID: Data File: Alaskan Copper Works PO M04514, F&BI 908157

908157-01 10x 908157-01 10x.046 ICPMS1

Instrument: ICPI
Operator: btb

Recovery:

Lower Limit: 60 Upper Limit: 125

Internal Standard: Germanium

Analyte:

Nickel

Copper

Zinc

Chromium

% Recovery: 92

49.9

Concentration ug/L (ppb) 263 230 331

### **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Alaskan Copper Works Client: Date Received: Not Applicable Project: PO M04514, F&BI 908157 Date Extracted: 08/20/09 Lab ID: I9-347 mb

I9-347 mb.035 Date Analyzed: 08/24/09 Data File: Matrix: Water Instrument: ICPMS1

Units: ug/L (ppb) Operator: btb

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 109 60 125

Concentration Analyte: ug/L (ppb)

Chromium <1 Nickel <1 Copper <1 Zinc <1

### **ENVIRONMENTAL CHEMISTS**

Date of Report: 08/27/09 Date Received: 08/20/09

Project: Metro Self Monitor, PO M04514, F&BI 908157

# QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 908097-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	<1	<1	nm	0-20
Nickel	ug/L (ppb)	<1	<1	nm	0-20
Copper	ug/L (ppb)	17.4	16.6	5	0-20
Zinc	ug/L (ppb)	19.2	18.7	3	0-20

Laboratory Code: 908097-01 (Matrix Spike)

		Percent				
Analyte	Reporting Units	Spike Level	Sample Result	Recovery MS	Acceptance Criteria	
Chromium	ug/L (ppb)	20	<1	101	50-150	
Nickel	ug/L (ppb)	20	<1	101	50-150	
Copper	ug/L (ppb)	20	17.4	103 b	50-150	
Zinc	ug/L (ppb)	50	19.2	102 b	50-150	

Laboratory Code: Laboratory Control Sample

		The state of	Percent	
Analyte	Reporting Units	Spike Level	Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	88	70-130
Nickel	ug/L (ppb)	20	92	70-130
Copper	ug/L (ppb)	20	89	70-130
Zinc	ug/L (ppb)	50	90	70-130

#### **ENVIRONMENTAL CHEMISTS**

# **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- $\operatorname{pr}$  The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 27, 2009



#### **INVOICE #09ACU0827-1**

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M04514, F&BI 908157 - Results of testing requested by Gerry Thompson for material submitted on August 20, 2009.

FEDERAL TAX ID #(b) (6)

end Report To sences Thomasin	SAMPLERS (signuture)	× .	Page of Of
ompany ALASKAN Compen Works  didress 628 5 Howard 81	PROJECT NAMENO.  MESTIO Self minited	PO# MOYSIY	TURNAROUND TIME    Standard (2 by caks)   RUSH
one # 206-87/WSFax #206-382-4309	REMARKS		SAMPLE DISPOSAL  Dispose after 30 days  Return samples  Will call with instructions

m 04514 01 8/20/05 H20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
MO4514 01 8/2/05 10:05 H20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Notes
γ/ν (*/ν (*/ν (*/ν (*/ν (*/ν (*/ν (*/ν (*	project s
	15
	o/m
	- 10 To Marcon III
Friedman & Bruya, Inc.  O12 16th Avenue West  Relinquibe 19 8/2/2	TIME
Redition of the Part of the Pa	10:36A
Fax (206) 283-504.1 Received by:	·

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 27, 2009

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on August 20, 2009 from the Metro Self Monitor, PO M04514, F&BI 908157 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0827R.DOC